

Flood Control Project Maintenance**2020 Channel Summary Report
Overall Unit and Item Ratings****Adin Community Service District**

Ash Creek

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

Dry Creek

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	M
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	N
	Encroachments	A

Flood Control Project Maintenance**2020 Channel Summary Report
Overall Unit and Item Ratings****DWR Sutter Maintenance Yard**

Big Chico Creek

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

Lindo Channel & Sandy Gulch

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	M
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

Little Chico Creek

Overall Unit Rating	Rated Item	Item Rating
M	Vegetation & Obstructions	M
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

Flood Control Project Maintenance**2020 Channel Summary Report
Overall Unit and Item Ratings****Fairfield Suisun Sewer District**

Laurel Creek

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	M
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

Ledgewood Creek

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

McCoy Creek

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	M
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

Union Avenue Diversion

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

Flood Control Project Maintenance**2020 Channel Summary Report
Overall Unit and Item Ratings****Madera County FCWCA****Ash Slough**

Overall Unit Rating	Rated Item	Item Rating
M *	Vegetation & Obstructions	A
	Shoaling / Sedimentation	M *
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

* Overall channel rating average is less than 0.2, however, U rated issues are present, so the overall rating is M instead of A.

Berenda Slough

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	M
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

Chowchilla River

Overall Unit Rating	Rated Item	Item Rating
M *	Vegetation & Obstructions	M *
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

* Overall channel rating average is less than 0.2, however, U rated issues are present, so the overall rating is M instead of A.

Fresno River

Overall Unit Rating	Rated Item	Item Rating
M	Vegetation & Obstructions	M
	Shoaling / Sedimentation	M
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

Flood Control Project Maintenance**2020 Channel Summary Report
Overall Unit and Item Ratings****Merced Streams Group**

Bear Creek

Overall Unit Rating	Rated Item	Item Rating
M	Vegetation & Obstructions	M
	Shoaling / Sedimentation	M
	Erosion / Bank Caving	M
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

Black Rascal Creek

Overall Unit Rating	Rated Item	Item Rating
M	Vegetation & Obstructions	U
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

Burns Creek

Overall Unit Rating	Rated Item	Item Rating
U	Vegetation & Obstructions	U
	Shoaling / Sedimentation	U
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

Mariposa Creek & Duck Slough

Overall Unit Rating	Rated Item	Item Rating
M	Vegetation & Obstructions	U
	Shoaling / Sedimentation	M
	Erosion / Bank Caving	M
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

Flood Control Project Maintenance**2020 Channel Summary Report
Overall Unit and Item Ratings****Merced Streams Group (cont.)**

Miles Creek

Overall Unit Rating	Rated Item	Item Rating
M	Vegetation & Obstructions	U
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	M
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

Owens Creek

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	M
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	M

Flood Control Project Maintenance**2020 Channel Summary Report
Overall Unit and Item Ratings****Placer County**

Truckee River

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

Flood Control Project Maintenance**2020 Channel Summary Report****Overall Unit and Item Ratings****San Joaquin County Flood Control and Water Conservation District****Duck Creek Diversion Channel**

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

North Littlejohn Creek

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

South Littlejohn Creek

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	M
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

South Littlejohn Creek North Branch

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	M
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

Flood Control Project Maintenance**2020 Channel Summary Report
Overall Unit and Item Ratings****Tehama County Flood Control and Water Conservation District**

McClure Creek

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	M
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	N
	Encroachments	A

Salt Creek

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A